



FLOW CHART

Sorbitol—First Step Fermentation—Sorbose—Second Step Fermentation—
Gulonic Acid — Esterification — Transformation — Acidization — Coarse Vc —
Dissolve &Decolor—Filter—Crystallization—Centrifugal—Drying
—Sieving— Inspection—Inner Packing—Outer Packing—Vitamin C

↓

CCP1

↓

CCP2

↓

CCP3

CCP1---SIEVING
CCP2---METAL DETECTOR
CCP3--- VACUUM DRYING